

# A 5-STEP GLIMPSE

into the  
Part Repair Process  
at ATS


## STEP 1

Equipment is inspected, barcoded, and logged into tracking system.



## STEP 2

Parts and components are disassembled (if submitted as an equipment package) and washed.



## STEP 3

Parts are repaired or replaced, each placed through rigorous testing and analysis.



## STEP 4

Equipment is reassembled with fixed/replaced parts and undergoes final testing in anticipated real-world conditions.



## STEP 5

Parts are shipped with a failure report and recommendations for extending the life of components.



# 15,000

# of spare and hard-to-find parts in ATS storage inventory



# 65,000

repairable parts with ATS repair and test procedures already on record



# ATS

Advanced Technology Services, Inc.

[www.advancedtech.com](http://www.advancedtech.com)

855-834-7604

[info@advancedtech.com](mailto:info@advancedtech.com)

